



**Meinberg Funkuhren**

**Antenna Short Circuit**

---

## Table of Contents

<b>Antenna Short Circuit</b> .....	3
<b><i>Problem Description</i></b> .....	3
<b><i>Possible Causes and Troubleshooting</i></b> .....	3
<b><i>Further Assistance</i></b> .....	3

# Antenna Short Circuit

## Problem Description

The error `Antenna Short Circuit` is shown on the front panel display or in the LANTIME Web Interface.

In the LANTIME Web Interface, this would be shown in the `Alarm` section on the `Main` page of the Web Interface, as shown by the screenshot below:



## Possible Causes and Troubleshooting

Possible causes and troubleshooting steps can be found in this [knowledge base article](#).

## Further Assistance

If further assistance is required, contact Meinberg Technical Support:  
<https://www.meinbergglobal.com/english/support/tech-support.htm>

— Manuel Schäfer [manuel.schäfer@meinberg.de](mailto:manuel.schäfer@meinberg.de), last updated 2023-05-16